LAW OFFICES

PAGE 07/13



At page 16, lines 1-4

The biasing members 338 are disposed at axially spaced apart positions about the spindle 308, and are suitably in the form of rubber bands extending through corresponding holes 342a 343a and 342b 343b in each of the ramp elements 348.